



Operation Instruction

A187+A177BK

Cable Pass Through Wall Plate + Low-Voltage Mounting Bracket



1 Use a drywall saw to cut a rectangular hole in the wall according to the size of the mounting bracket.



2 Screw the bracket to the wall. Run cables through the bracket.



3 Secure the brush part to the bracket.



4 Install the wall plate and tighten it with a screwdriver. Complete.

Note: The low voltage mounting bracket is sold separately.