

# Operation Instruction

## Ferrule Crimping Tool

GJ709

1



Strip the cable to the length of the ferrule.

2



Insert the wire into the ferrule.

3



Open the ferrule crimping tool and put the terminal into the jaw.

4




Press the handle.

5



Complete.

6



Tension test.