



1. Insert the cable cap



2. Put the Ethernet cable into the stripper



3. Strip the cable jacket




4. Arrange the wires



5. Cut the wires in oblique angle



6. Keep the wires neat, T568B



7. Put the wires into the RJ45 plug



8. Put the plug into the crimping tool. Crimp plug



9. Insure that the wires are pushed to the end of the plug's holes



10. Make the fixed buckle closer



11. Crimp fix buckle



12. Insert the cable cap into the RJ45 plug