

Operation Instruction

G601+C266


Mini Stripping Tool & Punch Down Stand




Prepare the mini stripping tool and Ethernet cable.



Strip the cable to a suitable length.



Use the wire stripper.



Turn around the stripper for a circle.



The cable jacket is stripped.



Pop the cable jacket.



Strip off the cable jacket.



Use the punch down stand mini stripper to punch down the keystone jack.