Operation Instruction

GJ670BL

RJ45 Pass Through Crimper

1




Unlock the RJ45 crimping tool first.

2



Strip the cable jacket.

3



Arrange and straighten eight wires.

4



Insert wires into the RJ45 connector.

5



Insert the connector into the cavity.

6



Press the crimping tool.

7



Crimp the RJ45 plug.

8



Crimp and cut off the excess wires at the same time.

9



Complete.